09/870, 619.

Knobbe Martens Olson & Bear LLP

Intellectual Property Law



2040 Main Street Fourteenth Floor Irvine, CA 92614 Tel 949-760-0404 Fax 949-760-9502 www.kmob.com

Rabinder N. Narula 949-721-2890 rnarula@kmob.com

March 29, 2006

Certificate

APR 0 6 2006

of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Re:

Title: VARIABLE VALVE TIMING STRUCTURE FOR OUTBOARD

MOTOR ENGINE

Letters Patent No. 6,910,450 B2

Issued: June 28, 2005

Our Reference: FS.16969US0A

Dear Sir:

Enclosed for filing is a Certificate of Correction in connection with the above-identified patent.

As the errors cited in the Certificate of Correction were incurred through the fault of the Patent Office, no fee is believed to be required. However, please charge our Deposit Account No. 11-1410 for any fees that may be incurred with this request.

Respectfully submitted,

Knobbe, Martens, Olson & Bear, LLP

Rabinder N. Narula Registration No. 53,371

Customer No. 20,995

Enclosures

2426813 032906

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,910,450 B2

Page 1 of 1

APPLICATION NO.

: 09/870,619

ISSUE DATE

: June 28, 2005

INVENTOR(S)

: Goichi Katayama

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At Column 20, line 15 in Claim 50, delete "driver" and insert -- driven --, therefor.

At Column 20, line 16 in Claim 50, delete "driver member is" and insert -- drive member is --, therefor.

At Column 20, line 16 in Claim 50, delete "driver member a" and insert -- driven member, a--, therefor.

At Column 20, line 33 in Claim 52, delete "valve is" and insert -- valve lies--, therefor.

At Column 20, line 34 in Claim 52, after "camshaft" insert -- opposite --.

At Column 20, line 37 in Claim 53, after "setting" insert -- section --.

2426496 032906

MAILING ADDRESS OF SENDER:

Rabinder N. Narula KNOBBE, MARTENS, OLSON & BEAR, LLP 2040 Main Street, 14th Floor Irvine, California 92614

DOCKET NO. FS.16969US0A